

— — ABERRATED WAVEFRONTS AND RAYS— PERFECT WAVEFRONTS AND RAYS

FIGURE 1 (PRIOR ART)






FIGURE 2










FIGURE 5









FIGURE 6G



	<del> </del>	<b>~</b> −	/ <b>!</b>	M3 / M4		
				M3 M4		
				M5		
M2		M	1		4	FP 502
						002

## FIGURE 7



## FIGURE 8




FIGURE 9






FIGURE 10A




FIGURE 10B






FIGURE 11B




FIGURE 11C